








d_0	$\varnothing 8\text{mm}$

$h_{nom}=70\text{mm} \mid t_{fix2}=0...10\text{mm}$		
HUS3-C 8	t_{fix1}	$t_{fix1}+t_{fix2}$
8x75	5 mm	5...15 mm
8x85	15 mm	15...25 mm
8x100	30 mm	30...40 mm

h_{nom}	h_1
60	70
70	80

h_{nom}	$h_{1.nc}$	$h_{1.nc}$
60	94	70
70	104	80








d_0	$\varnothing 8\text{mm}$

$h_{nom1}=50\text{mm} \quad h_{nom2}=60\text{mm} \quad h_{nom3}=70\text{mm}$			
HUS3-C 8	t_{fix1}	t_{fix2}	t_{fix3}
8x65	15 mm	-	-
8x75	25 mm	15 mm	-
8x85	35 mm	25 mm	15 mm
8x100	50 mm	40 mm	30 mm

h_{nom}	h_1
50	60
60	70
70	80








h_{nom}	$h_{1.nc}$	$h_{1.nc}$
50	84	60
60	94	70
70	104	80











d_0	Ø 8mm	Ø 6mm

$h_{nom2}=60mm$	
HUS3-C 8	t_{fix2}
8x65	-
8x75	15 mm
8x85	25 mm
8x100	40 mm



d_0	Ø 8mm

min. $t_{fix}=5mm$	
HUS3-C 8	t_{fix}
8x65	5 mm
8x75	5 mm
8x85	15 mm
8x100	30 mm



	SIW 22-A 1/2" (01)	SIW 6AT-A22 1/2" (01)	SIW 22T-A 1/2" (01)	SIW 22T-A 3/4" (01)	SIW 9-A22 3/4" (01)
HUS3-C 8	✓	✓	✓	✓	✗